

Required Tool List for Welding and Cutting Fall 2020 Semester

(All tools and supplies are to be bought by the Welding student
by the end of the first week of the semester.)

Safety Glasses

6 Particle Masks (NIOSH N95 Particulate Respirator)

2 Pair Welding Gloves

1 Pair Cutting Goggles With #4 or #5 Lens (2"x4" Lens)

Welding Cap

1 Pair Leather Cape Sleeves or Jacket

Welding Hood With #10 Filter Lens or Auto Dark

Padlock (for Lockers)

Notebook (3-Ring With Ruled and Graph Paper), Pens, Pencils, and Large Permanent Markers

Dark Cotton Work Clothes—Blue Demin (Heavy Dark 100% Cotton Shirt With Button Down Pockets
and Heavy Dark 100% Cotton Work Pants With No Cuffs or Frayed Edges) All Clothing Must Be Tightly
Woven and Flame Resistant.


Boots or Work Shoes (All Work Shoes or Boots Must Be All Leather. No Canvas Inside or Out.) High
Top and Steel Safety Toes. Boots May Be Either Pull-On or Lace-Up.

Required Textbooks for Welding and Cutting

NCCER Construction Core—5th Edition Trainee Guide

NCCER WELDING LEVEL I—5th Edition Trainee Guide

NCCER WELDING LEVEL II—5th Edition Trainee Guide



EAST CENTRAL
COMMUNITY COLLEGE